

EX 6.4) How to align a rafter problem

Since the longitudinal resistance, R is not changing,
the force required to break depends only on the
ratio of the supporting lever arms:

$$\boxed{\frac{T}{X} = \frac{ac}{bc}}$$